



westermo® **INFORMATION**

www.westermo.com

**Firmware Release Note
for:**

TDW-33	4101-0614
TD-36	4101-0714
TD-36 485	4101-0814
TR-36	4101-1414

Westermo Teleindustri AB

New features:

- Added V.23 HDX/FDX multi-drop support
- Added Voice mode support (DTMF and Dual-tone detection/generation)
- Information string (AT*WI command)
- Direct mode via DIP-Switch 3:3 and 3:4
- RTS/CTS flow control only active in data mode
- Fix for transfer parity bit over the line in 7 data bit mode
- Sets DCD after connect string has been sent to DTE
- S-Register not corrupt modulation settings
- Added the timeout parameter to IO SMS.
- Supervisor function will now do a fast disconnect
- More PLC's supported

Corrected problems:

- Normal buffer mode, buffering DTE transmit data
- V.32 LL monitoring
- Minor fixes

Known problems:

- No new ones